


Document Number: RA-OPF-008	EQUIPMENT DEFECT REPORT	EDGE ROPE
Date of issue: 12/05/2021		
Issue No.: 001		
Page 1 of 2		

Job Number	SPRAT Training	This non-conformance report must be completed for any damaged item of equipment which has failed pre-use inspection. Defective items should immediately be marked "do not use" and securely quarantined. This equipment defect report should be completed before the item is repaired or disposed of.
Location	EDGE Rope Training Center	
Item	Petzl I'D	
Unique Number	T-DC-5	

Description of defect			
Plastic part to the right side of the cam has popped out without breaking any part of the I'D.			
Cause of defect			
Incorrect installation of rope.			
Report by	Oktay DAVIDOV	Position	Rope Access Manager
Signature		Date	24 Aug 2022

FOR OFFICE / STORES USE	
Has this been a recurring problem?	
If so has the distributor / manufacturer been informed?	
Further action taken?	

Closed out by		Position	
Signature		Date	